	Туре	Hits	Search Text	DBs	Time Stamp
1	IS&R	420	(219/108).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:20
2	IS&R	304	(219/109).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:12
3	IS&R	986	(219/110).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:14
4	IS&R	874	(219/117.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:14
5	IS&R	3	(("3940624") or ("5961854") or ("6057523")).PN.	USPAT	2007/04/14 11:17
6	BRS	8	("4596917" "4861960" "5343011" "5440092" "5575934").PN. OR ("6057523").URPN.	US-PGPUB; USPAT; USOCR	2007/04/14 11:17
7	BRS	4	("3363086" "4859825" "5844194").PN. OR ("5961854").URPN.	US-PGPUB; USPAT; USOCR	2007/04/14 11:19
8	BRS	11	("3114836" "3191441" "3405270" "3462602" "3633031").PN. OR ("3940624").URPN.	US-PGPUB; USPAT; USOCR	2007/04/14 11:19

	Туре	Hits	Search Text	DBs	Time Stamp
9	IS&R	1262 33	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:20
10	IS&R	1217 72	("250").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:20
11	BRS	2469 08	S9 or S10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:21
12	BRS	16	\$11 and ((resistance or spot) near5 weld\$3) near20 (monitor\$3 or analy\$4 or quality or integrity) near50 (foil\$1 or strip\$1 or tape\$1)	US-PGPUB; USPAT; EPO: JPO:	2007/04/14 11:36
13	BRS	49	or analy\$4 or quality	US-PGPUB; USPAT;	2007/04/14 11:39
14	BRS	16	((resistance or spot) near5 weld\$3) near50 (foil\$1 or strip\$1 or tape\$1) near50 (image or optical or visual\$7)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:43

	Туре	Hits	Search Text	DBs	Time Stamp
15	BRS	490	weld\$3 near50 (foil\$1 or strip\$1 or tape\$1) near50 (image or optical or visual\$7)	EPO; JPO;	2007/04/14 11:41
16	BRS	319	weld\$3 near10 (foil\$1 or strip\$1 or tape\$1) near10 (image or optical or visual\$7)	EPO; JPO;	2007/04/14 11:41
17	BRS	189	weld\$3 near10 (foil\$1 or strip\$1) near10 (image or optical)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:41
18	BRS	56	weld\$3 near5 (foil or strip) near5 (image or optical)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/14 11:43
19	BRS	274	(((resistance or spot) near5 weld\$3) near50 (foil\$1 or strip\$1 or tape\$1)).clm.	US-PGPUB; USPAT	2007/04/14 11:45
20	BRS	2	(((resistance or spot) near5 weld\$3) near50 (foil\$1 or strip\$1 or tape\$1) near50 (image or optical or visual\$7)).clm.	US-PGPUB; USPAT	2007/04/14 11:44

	Туре	Hits	Search Text	DBs	Time Stamp
21	BRS	3	(((resistance or spot) near20 weld\$3) near100 (foil\$1 or strip\$1 or tape\$1) near100 (quality or monitor\$3 or analy\$4 or integrity)).clm.	US-PGPUB; USPAT	2007/04/14 11:46
22	BRS	2	(((resistance or spot) near5 weld\$3) near50 (foil\$1 or strip\$1 or tape\$1) near50 (quality or monitor\$3 or analy\$4 or integrity)).clm.	US-PGPUB; USPAT	2007/04/14 11:45